

September 01, 2024

Caliber Energy
10497 – 92nd Street
High Level, Alberta
T0H 1Z0

CERTIFICATION

Equipment:	Bowen Swivel Assembly
Model:	85 Ton
Serial No.:	0142
Owner:	Caliber Energy
Repair Facility:	Tri-Service Oilfield Manufacturing Ltd. (W.O. 76536)
Inspection Report No.:	TSM 76536


Tri-Service Oilfield Manufacturing technician performed examination of this swivel assembly as indicated on the report as listed above on July 25 and August 12, 2024. The swivel assembly was completely disassembled and cleaned or sandblasted.

Tri-Service Oilfield Manufacturing technician provided magnetic particle inspection services.

Final NDT inspection revealed no defects. As a result of the inspections and review of repairs, it is our opinion that this swivel assembly may be safely returned to service within the manufacturer's original ratings and specifications.

This certification is valid for 1250 operating days, as per recommendations provided by CAOEC RP-2.0, or until the swivel assembly is damaged either as a result of operation, transportation or handling.

Jim Ip, P.Eng.
APEGA Permit No. P13591
Ty Engineering File No.: E24-22574



September 01, 2024

ID.# 68573